

Name	Brookview Elem	District	Waukee CSD
Address	8000 E.P. True Parkway IA, West Des Moines, 50266	Scope	<input checked="" type="checkbox"/> All regularly occupied rooms in contact with the ground, or above spaces in contact with the ground, were tested.
Conducted By	Garry Pickard	Phone	5154185258
# Test Kits Used	82	Dates	01/22/2024 - 03/22/2024

Test Results

Test 1:	# Rooms Tested:	64	#Rooms 4.0 pCi/L or above:	5
----------------	------------------------	----	-----------------------------------	---

Quality Controls

Testing was conducted on weekdays when school was in session. Closed building conditions were maintained. Advanced notification was given to staff, teachers and building managers. Blanks and duplicates were deployed. Routine maintenance including HVAC inspection and service per best practice occurred prior to testing.

Notes

Please note that the above test results included (a) second short-term(s) within 60 days in spaces with results at or above the EPA'S action level of 4 pCi/l.

Initial elevations were fixed with the following basic corrective measures:

- Ventilation adjustments
- Filter changes
- Ensuring snow was not blocking ventilation on roofs

While Test 2 and 3 results are not seen separately above, Test 2 was conducted from 2/26 - 3/1/2024. Test 3 was conducted from 3/18 - 3/22/24.

Due to corrective measures changing initial test conditions, Tests 2 and 3 were averaged to determine if further action was needed. No additional action was needed due to averages coming back below 4 pCi/l.

No further testing is necessary for 5 years or per district's School Radon Plan Testing Rotation Calendar.

Next Steps

Re-test any mitigated spaces every 2 years. Re-test after any major renovations to the building or HVAC systems. Allow Energy Association of Iowa Schools to remind your school district when it's time to once again participate in the School Radon Training & Support System!

Radon Testing Results Summary by Building

2 of 4

Report Date

05/28/2024

Name	Eason Elem	District	Waukee CSD
Address	605 SE Boone Dr IA, Waukee, 50263	Scope	<input checked="" type="checkbox"/> All regularly occupied rooms in contact with the ground, or above spaces in contact with the ground, were tested.
Conducted By	Garry Pickard	Phone	5154185258
# Test Kits Used	66	Dates	01/21/2024 - 01/26/2024

Test Results

Test 1:	# Rooms Tested:	56	#Rooms 4.0 pCi/L or above:	0
----------------	------------------------	----	-----------------------------------	---

Quality Controls

Testing was conducted on weekdays when school was in session. Closed building conditions were maintained. Advanced notification was given to staff, teachers and building managers. Blanks and duplicates were deployed. Routine maintenance including HVAC inspection and service per best practice occurred prior to testing.

Notes

No further testing is necessary for 5 years or per district's School Radon Plan Testing Rotation Calendar.

Next Steps

Re-test any mitigated spaces every 2 years. Re-test after any major renovations to the building or HVAC systems. Allow Energy Association of Iowa Schools to remind your school district when it's time to once again participate in the School Radon Training & Support System!

Radon Testing Results Summary by Building

3 of 4

Report Date

05/28/2024

Name	Maple Grove Elem	District	Waukee CSD
Address	1455 98th ST. IA, West Des Moines, 50266	Scope	<input checked="" type="checkbox"/> All regularly occupied rooms in contact with the ground, or above spaces in contact with the ground, were tested.
Conducted By	Garry Pickard	Phone	5154185258
# Test Kits Used	75	Dates	01/22/2024 - 01/26/2024

Test Results

Test 1:	# Rooms Tested:	64	#Rooms 4.0 pCi/L or above:	0
----------------	------------------------	----	-----------------------------------	---

Quality Controls

Testing was conducted on weekdays when school was in session. Closed building conditions were maintained. Advanced notification was given to staff, teachers and building managers. Blanks and duplicates were deployed. Routine maintenance including HVAC inspection and service per best practice occurred prior to testing.

Notes

No further testing is necessary for 5 years or per district's School Radon Plan Testing Rotation Calendar.

Next Steps

Re-test any mitigated spaces every 2 years. Re-test after any major renovations to the building or HVAC systems. Allow Energy Association of Iowa Schools to remind your school district when it's time to once again participate in the School Radon Training & Support System!

Name	Grant Ragan Elem (re-test 408)	District	Waukee CSD
Address	645 NE Dartmoor Dr. IA, Waukee, 50263	Scope	<input checked="" type="checkbox"/> All regularly occupied rooms in contact with the ground, or above spaces in contact with the ground, were tested.
Conducted By	Garry Pickard	Phone	5154185258
# Test Kits Used	83	Dates	01/22/2024 - 03/22/2024

Test Results

Test 1:	# Rooms Tested:	66	#Rooms 4.0 pCi/L or above:	1
----------------	------------------------	----	-----------------------------------	---

Quality Controls

Testing was conducted on weekdays when school was in session. Closed building conditions were maintained. Advanced notification was given to staff, teachers and building managers. Blanks and duplicates were deployed. Routine maintenance including HVAC inspection and service per best practice occurred prior to testing.

Notes

Please note that the above test results included (a) second short-term(s) within 60 days in the space with a result at or above the EPA'S action level of 4 pCi/l.

The initial elevation was fixed with the following basic corrective measures:

- Ventilation adjustments
- Filter changes
- Ensuring snow was not blocking ventilation on roofs

While Test 2 and 3 results are not seen separately above, Test 2 was conducted from 2/26 - 3/1/2024. Test 3 was conducted from 3/18 - 3/22/24.

Due to corrective measures changing initial test conditions, Tests 2 and 3 were averaged to determine if further action was needed. No additional action was needed due to averages coming back below 4 pCi/l.

No further testing is necessary for 5 years or per district's School Radon Plan Testing Rotation Calendar.

Next Steps

Re-test any mitigated spaces every 2 years. Re-test after any major renovations to the building or HVAC systems. Allow Energy Association of Iowa Schools to remind your school district when it's time to once again participate in the School Radon Training & Support System!